

# **Field Note Record**

-4 <b>/</b>	ai iiioiii oi iiaii	sportation						
Contract No. Station 009359 Section 3		Mile/Line:		C/S	C/S			
		I-182						
Staked by	Date	Work Started Date		Work Completed Date				
Survey		10/14/2019						
9/25/2019								
Calculated by	Date	Checked by	Date	Inspector	Date			
Scott Busby		E. Knudson		Scott Busby	11/5/19			
11/5/2019		11/21/2019						

ITEM NO. 15 Section 3 - I-182, US-395 & SR-240 Change Order # 4 BEAM GUARDRAIL TYPE 31

Est.#8

### **Group Number 23**

10/16/2019 - I-182

- Station MP 1.40 WB LT EB See attachment below
- 87.5 LF of Beam Guardrail Type 31
- (87.5 / 6.25)+1 = Total of **15** wood posts and blocks
- 8 steel posts for the end terminal

10/16/2019 - I-182

- Station MP 5.40 R1 Exit 5B off ramp mp 0.19 WB RT See attachment below
- 25 LF of Beam Guardrail Type 31
- (25 / 6.25)+1 = Total of **5** wood posts and blocks
- 8 steel posts for the end terminal

Sub Total = 87.5 + 25 = 112.5 LF of Beam Guardrail Type 31

= 15 + 5 = 20 Wood Posts and Blocks

= (8 \* 2) = **16** Steel posts for the end terminals

#### **Group Number 24**

10/17/2019 - I-182

- Station MP 11.75 C1 Exit 12A/B off ramp mp 0.17 EB RT See attachment below
- 62.5 LF of Beam Guardrail Type 31
- (62.5 / 6.25)+1 = Total of **11** wood posts and blocks
- 8 steel posts for the end terminal

10/17/2019 - I-182

- Station MP 14.01 WB RT
- 12.5 LF of Beam Guardrail Type 31
- (12.5 / 6.25)+1 = Total of **3** wood posts and blocks
- 8 steel posts for the end terminal

Sub Total = 62.5 + 12.5 = 75 LF of Beam Guardrail Type 31

= 11 + 3 = **14** Wood Posts and Blocks

= (8 \* 2) = **16** Steel posts for the end terminals

# **Group Number 27**

10/21/2019 - US-395

- Station MP 19.44 P1 Sylvester Road off ramp mp 0.19 NB LT See attachment below
- 150 LF of Beam Guardrail Type 31
- (150/ 6.25)+1 = Total of **25** wood posts and blocks
- 6 steel posts for the end terminal

# Sub Total = 150 LF of Beam Guardrail Type 31

- = 25 Wood Posts and Blocks
- = **6** Steel posts for the end terminals

### Total = 112.5 + 75 + 150 = 337.5 LF of Beam Guardrail Type 31

= 20 + 14 + 25 = **59** Wood Posts and Blocks

= (8 \* 4) + 6 = **38** Steel posts for the end terminals

#### Note:

# Measured by wheel and counted

Item Num	Material Brand Name/Model Type	Manufacturer	Brand Name/Model Type	RAMS/QPL Ref. No.	Appr/Acc Code	Basis of Accept
015.02	Beam Guardrail Thrie Beam Elements and Components	Trinity Highway Products, LLC		QPL-0001	2215 /	Mfr. Cert. per Stnd. Spec. 1-06.3
015.03	Beam Guardrail Wood Post and Blocks	Superior Wood Treating		QPL-0005	2550 /	Lumber Grading Stamp or Grading Certificate and Certificate of Treatment. (If Aquatic Envir. Std. Spec. 9-09.3 (1) Applies)
015.04	Beam Guardrail Steel Post and Blocks	Trinity Highway Products, LLC`		QPL-0002	2215 /	Mfr. Cert. per Stnd. Spec. 1-06.3

Item Num	Item Description	Grp	Date Work Complete	Unit	Quantity	Ledger Entry No.	Pos Init.	sted By Date	Chec Init.	ked By Date	Est. No.
0015	BEAM GUARDRAIL TYPE 31	23	10/23/20	L.F.	112.5	361	EK	11/21/19			8
0015	BEAM GUARDRAIL TYPE 31	24	10/23/20	L.F.	75	362	EK	11/21/19			8
0015	BEAM GUARDRAIL TYPE 31	27	10/23/20	L.F.	150	363	EK	11/21/19			8

#### **Attachments**



I-182 mp 1.4 WB LT.pdf Adobe Acrobat Document 100 KB



I-182 mp 5.22 WB RT.pdf Adobe Acrobat Document 99.5 KB



I-182 mp 11.75 EB RT.pdf Adobe Acrobat Document 98.3 KB



Section3 1674\_001.pdf Adobe Acrobat Document 79.8 KB

DOT Form IP 422-635ER EF Revised 4/2009